

TDEC - Division of Water Resources Jackson Field Office

ICIS NPDES Facilities Inspection Report

				Fac	cility Data							
NPDES ID: TNR12	1787		Facility Site Name	Thomsen Farm 10K								
			Address	Oil Well Road								
Permit Eff. Date: 12/17/2015 Permit E			Permit Exp Date:	9/30/202	9/30/2021				SIC Code:			
			Compli	iance M	onitoring Info	rmati	on					
Compliance Monito	ring Acti	vity Name	tormwater Construc	tion Non-	Sampling							
		* If E	Bio Monitoring is sele	ected abov	ve, select the meth	od used	d:					
Compliance Monito	ring Acti	vity	valuation									
成。但是 须			Compli	ance Mo	onitoring Date	s/Tim	nes					
Entry Date/Time (mm/dd/yyyy hh:mm): 12/9/2016 11:				Exit Date/Time (mm/dd/yyyy hh:mm): 12/9/2016 12:30								
			SE EN COLOR	acility F	Representative	es						
					Kirk Arment, 731-2	222-50	69					
On-Site Representa	tive(s)Tit	le, Phone Nur	mber	Responsible Official(s), Title, Phone Number								
			Statu	te and 9	Section Inform	ation						
Federal Statute:	CWA - 0	Ilean Water A	ıct		State Statute:	Quality Contro	uality Control Act					
Programs:	Programs: NPDES-Stormwater Construction											
Compliance Monitoring Reason: Core Program												
Compliance Moni	toring A	gency Type:	: State	Agency Name:					e: TDEC - DWR			
Did EPA assist/Inspe	ection?	No		Time Ph	nysically conductin		Hours:	2				
Inspection Type: State				Comp	oliance Monitoring							
Lead Agency: State				Com	pliance Monitoring	Unrated	ated					
If Joint Inspection, v	vhat was	the purpose o	of the other party?									
		Areas Ev	aluated During	Inspect	tion (Check on	ly tho	se areas e	valuated)		PATEL PAREN		
Permit			☐ Self	- Compli	ance Program			Pretreatmer	nt	M		
Records / Records			Con	Compliance Schedule				Pollution Prevention				
Facility Site Review			☐ Lab	Laboratory			\boxtimes	Storm Water				
			□ Оре	Operations & Maintenance				Combined Sewer Overflow				
☐ Flow Measurement ☐			☐ Sluc	dge Hand	lling / Disposal		Sanitary Sewer Overflow					
			Comp	liance N	Monitoring Sur	nmar	у			A BUTTON		
Construction comple	ete. Site p	pave and sodo	ded. Appears to be s	stable.								
ATT AFTER			EPA	and Sta	te Representa	tives		TEL STREET				
Diem ?	5 C	restA		TDEC-DWR/Jackson EFO/731-512-1308					12/9/2016			
Inspector's signature				Agency / Office / Phone					Date /			
(mer Sant?				C-DWR/Ja	ackson EFO/731-51	12/	12/9/14					
Manager's Signature				ency / Offic	/	(4						

(Note: This form can only be printed to an XPS document, then saved for later use.)



TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION

Division of Water Resources

William R. Snodgrass Tennessee Tower, 312 Rosa L. Parks Avenue, 11th Floor, Nashville TN 37243 1-888-891-8332 (TDEC)

Compliance Inspection for General NPDES Permit for Stormwater Discharges from Construction Activities (CGP)

Site/Project Name: Thom		Thomse	omsen Farms, Phase III and IV - Thousen Faen 10K						NPDES Tracking Number:			TNR121787
Site/I roject ivalie.			Harms, I have III and I'					- \	Date Coverage was Issued			17-DEC-15
Street Address or Oil Well Road			Road						Start date:			15-DEC-15
Location:									Estimated end date:			01-JUN-16
				ce space withi	space within the larger development of				Latitude (dd.dddd):			35.6895
Description: Thomsen Farms on Lot 501				Longitude (-d					dd):	-88.86283		
County(ies): Madison EFO:			EFO: Jackson	Jackson MS4 Jurisdicti			Jackson			Acres Disturbed:		
Juriso					diction.				Total Acres:	_		
Nan	ne of Permittee (D	eveloper/	Operator): First Cho	ice Property &	& Deve	lopmer	nt, LLC					
Name of Official Contact: Kirk Arment Email: Karr						firstch	oicepd.coi	m			Contact Phone	e: 731-222-5069
Address: 219 U.S Highway 45 City: Huml									State: TN			Zip: 38343
Che	ck List (office & fiel	d checks)			Yes	No			Cor	mmer	nts	
1	Does the site have	CGP cov	erage?								1 -0	
2	Is NOC posted on	site?				X	Hes	Liled	NOT ¢	rer	nved all	signage
3	Have the site cont	ractors sig	gned the NOI?		\boxtimes				ş .			0
4	Is the current SWI	PPP avail	able for review?			X	No	one	on-site	,		
5	Are EPSCs in acc	ordance v	vith SWPPP?		X							
6	Are EPSCs install	ed proper	ly and functional?		A							
7	Are inspection rep	<u> </u>				V	No	and a	m- site	,		
8	Is the proper buffe									N/A		
9		length of	re areas on the site? If time has been more the		M						3	0
10	Are more than 50					M						
11	Has sediment disc				T	V						
12			to waters of the State?	?	ĦΠ	1						8
13			rations to waters of th		怈	TO THE						
14	Are there violation	ns of an e								N/A		€
15 Other pollutants/discharges or unusual problems?				?		X						
16	Project is complete and stable with no construction-related											2
General Comments: Site is paved & sodded. Appears to be steeble.												
GCI	Site is	s par	ed & solde	t. App	ears	to	be .	Steel	ole.			
								×	(6)			
	Routine 🔲		Comprehensive [11	Co	mplaint			Follow Up		Termin	ation 🛛
On-	Site Contact (if avai	ilable)										
	Site Contact Name (On-Site Con	ntact Title:				Signature	2;			Date:
TD	EC Personnel/Inform	mation							T		EFO: Name a	nd Address
TDEC Personnel/Information Inspector's Name (Print): Signature:						Date: 12 0 3 1 Jackson				ckson Environme	ntal Field Office	
GREGORY S OVERSTREET Change Just Time: 12:15 por Jackson, TN 38305												